

Selected Soil Interpretations— Camp, Franklin, Morris, and Titus Counties, Texas							
Map symbol and soil name	Pct. of map unit	For - construction limitations for haul roads/log landings		For - road suitability (natural surface)		For - soil rutting hazard	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Na—Nahatche loam silty clay loam, frequently flooded							
Nahatche	80	Severe		Poorly suited		Severe	
		Flooding	1.00	Flooding	1.00	Low strength	1.00
		Low strength	0.50	Wetness	0.50		
				Low strength	0.50		
SaC—Sacul fine sandy loam, 2 to 5 percent slopes							
Sacul	90	Slight		Well suited		Moderate	
						Low strength	0.50
SaD—Sacul fine sandy loam, 5 to 15 percent slopes							
Sacul	85	Slight		Moderately suited		Moderate	
				Slope	0.50	Low strength	0.50

Data Source Information

Soil Survey Area: Camp, Franklin, Morris, and Titus Counties, Texas
 Survey Area Data: Version 7, Oct 27, 2009